

Onagawa Seismically-Induced HEAF Fire Event

- NPP under full power before the seismic event occurred on March 11, 2011
- Cause of the event combination:
 - Suspended breaker inside the high-voltage power distribution panel swinging widely due to the seismic vibration damaging disconnecting parts of the pertinent breaker




Figure 1.2-2. Onagawa Arching Scenario